

ANALISA LAJU KOROSI GALVANIS MATERIAL *FORK* DAN *FERRULE* PADA KOMPONEN *NOSE LANDING GEAR*

Disusun Oleh:

**RULY ERVITA SARI
NIM: 16050015**

ABSTRAK

Pada inspeksi pesawat PK-SFA ditemukan *crack* pada bagian *fork nose landing gear*. Posisi *Fork* menempel dengan *Ferrule*, kondisi seperti hal ini erat kaitannya dengan korosi galvanis dan dapat memicu terjadinya *crack* ataupun kegagalan pada komponen yang bisa membahayakan keselamatan pesawat udara. Korosi sendiri diakibatkan karna adanya interaksi logam dengan logam serta lingkungan sekitarnya.

Tujuan penelitian kali ini adalah untuk mengetahui laju korosi galvanis antara material *fork* dan *ferrule* dalam media NaCl 3,5% dengan variasi waktu perendaman menggunakan alat *Rectifier*. Benda uji dibuat berbentuk persegi kemudian dilakukan *polishing* untuk mendapatkan permukaan yang bersih dari coating. Sebelum dilakukan uji korosi, masing-masing material komponen tersebut dilakukan uji komposisi terlebih dahulu untuk mengetahui jenis materialnya. Laju korosi dianalisis menggunakan metode kehilangan berat dan metode beda potensial. Pengujian lain yang dilakukan untuk mendukung penelitian kali ini yaitu Uji Mikro dari permukaan material yang telah dilakukan uji korosi.

Hasil pengujian komposisi didapatkan kandungan Magnesium (Mg) sebesar 2,087% dan Seng (Zn) sebesar 5,411% serta kandungan Aluminium (Al) senilai 90,65% serta terdapat unsur-unsur panduan lainnya. Dan di hasilkan *Grade* Al100 untuk komponen *ferrule*. Pada komponen *Fork* kandungan karbon sebesar 0,388% dan kandungan Besi (Fe) senilai 95,78% serta terdapat unsur-unsur panduan lainnya yang rendah kemudian di hasilkan *Grade* Fe110. Laju korosi yang di hasilkan dari perhitungan metode beda potensial yaitu untuk menit ke-4 = 0,759 volt/menit, menit ke-6 = 0,506 volt/menit, dan ke-8 = 0,379 volt/menit. Nilai laju korosi yang di dapat dengan metode kehilangan berat material Al yaitu spesimen 1 sebesar 1.057 mmyr, spesimen 2 sebesar 709 mmyr, spesimen 3 sebesar 2.453 mmyr, dan pada material Fe spesimen 1 sebesar 1.510 mmyr, spesimen 2 sebesar -2.908 mmyr, spesimen 3 Sebesar 1.361 mmyr.

Kata Kunci: Galvanis, *Ferrule*, *Fork*, *Decouplet*, *Rectifier*, kehilangan berat, potensial.

ANALYSIS OF GALVANIZED CORROSION RATE OF FORK AND FERRULE MATERIALS ON NOSE LANDING GEAR COMPONENTS

By: Ruly Ervita Sari

16050015

ABSTRACT

On inspection of the PK-SFA aircraft, cracks were found on the fork nose landing gear. The position of the Fork is attached to Ferrule, conditions like this are closely related to galvanic corrosion and can trigger cracks or failures in components that can endanger the safety of the aircraft. Corrosion itself is caused by the interaction of metal with metal and the surrounding environment.

The purpose of this study was to determine the rate of galvanic corrosion between fork and ferrule materials in 3.5% NaCl media with variations in immersion time using a rectifier. The test object is made into a square shape and then polished to get a clean surface from the coating. Prior to the corrosion test, each component material is tested for composition to determine the type of material. The corrosion rate was analyzed using the weight loss method and the potential difference method. Another test carried out to support this research is the Micro Test of the surface of the material that has been tested for corrosion.

The results of the composition test showed that the content of Magnesium (Mg) was 2.087% and Zinc (Zn) was 5.411% and the content of Aluminum (Al) was 90.65% and there were other guiding elements. And produced Grade Al100 for ferrule components. In the Fork component, the carbon content is 0.388% and the Iron (Fe) content is 95.78% and there are other guide elements that are low, then Grade Fe110. The corrosion rate that is generated from the calculation of the potential difference method is for the 4th minute = 0.759 volts/minute, the 6th minute = 0.506 volts/minute, and the 8th minute = 0.379 volts/minute. The value of the corrosion rate obtained by the weight loss method of Al material is 1.057 mmyr, specimen 2 is 709 mmyr, 3 is 2.453 mmyr, and for Fe material, specimen 1 is 1.510 myr, specimen 2 is -2.908 mmyr, specimen 3 amounted to 1.361 mmyr.

Keywords: Galvanized, Ferrule, Fork, Decouplet, Rectifier, weight loss, potential.